

**graphics mounting procedure. (except gas tank decals)**

- step 1 - clean area with isopropyl alcohol & wipe dry with a clean dry cloth before alcohol evaporates.
- step 2 - apply decals and wait 48 hours before riding.

**gas tank decal mounting procedure. (if applicable)**

- step 1 - drain gas tank & leave in a well ventilated area for 72 hours with cap off.
- step 2 - clean area with isopropyl alcohol & wipe dry with a clean dry cloth before alcohol evaporates.
- step 3 - apply decals and wait 48 hours before filling tank with gas.